

How to Repair a Ripped Cloth-Fleece Jacket

This guide will show one how to repair a minor rip in a Cloth-Fleece Jacket, involving sewing, a needle, and thread.

Written By: Austin-Lewis Craig



INTRODUCTION

This guide will consist of steps, **instructing one to repair a rip in a cloth-fleece jacket**, *using a needle, thread, and/or a thimble*. *Caution/Hazard* The needle is sharp and a thimble is *advised* to be used for safety.


While it *may* help one learn to sew (or do something necessary within the process), this guide *will* especially assist one in **sewing closed a rip in cloth-fabric** jacket, garment, etc.



TOOLS:

- Sewing Needle (1)
- Thread (1)
- Sewing Kit (1)
- Utility Scissors (1)

Step 1 — How to Repair a Ripped Cloth-Fleece Jacket






Guide ID: 100062 - Draft: 2019-08-01

 Identify the hole/rip, its length and the thread that matches the fabric's color of the jacket (or desired color).

Step 2




 Thread needle and knot the thread onto the needle, so that the needle and thread are inseparable.

Step 3



• Insert less dominant hand - hand one doesn't write with - into the inside of the jacket, <u>before holding</u> the flaps of the hole together as to show how the loose fabric edges will align.

Step 4



• (Starting at one end of the rip) using one's more dominant hand, insert the threaded needle through one fabric flap, before returning the needle back through the other fabric flap, as to loop beneath the rip.

Step 5



 Repeat step 4 [looping beneath and above the rip] until the threads have looped the rip tight and the thread is hanging from the opposite end of the rip at which one started.

Step 6



 Knot the thread multiple times - 2 to 4 times approximately - and remove the excess thread following the knot (use scissors for best results).

Step 7



 Wash jacket [or get dry cleaned if necessary] and repeat steps if needed.

To undo the threading [as to start over, or simply remove the stitch], only snip/cut the applied threading along the rip and remove the excess threading.