

# Navi Falk Neo550 Battery Replacement

Replacing the battery with the Navi Falk Neo550

Written By: John Maier



# Step 1 — Unscrew lower edge cover



• Using a PH 0 screwdriver, loosen the four screws on the underside of the device.

# Step 2 — Release the screen



• Pull the plastic card at the lower corners, starting at the bottom of the screen.


#### Step 3 — Remove the edge cover



- At one of the bottom corners, remove the edge cover by sliding a plastic card from the front of the navigation system under the edge.
- The edge strip is attached with double-sided tape, the plastic card can be pushed with a sawing movement gradually under the side cover

A Caution: At the two lower corners, the cover strip is inserted into the housing with a latching lug.

#### Step 4 — remove inner edge cover




• Use the screwdriver PH 0 to remove the two screws at the upper edge.

# Step 5 — Separate wall




Pull a plastic card between the wall and the side panel to separate them. After the sides also separate the upper edge.

# Step 6 — remove inner edge cover




• Pull out the inner edge cover between the screen and the rear panel.

# Step 7 — Disconnect the battery cable




• Pull the battery cable downwards, then out from the guide nose.



# Step 8 — Disconnect the battery cable


- Remove the adhesive tape from the battery.
- Pull plug out of socket.

# Step 9




The battery is glued to the housing with a very tough adhesive tape. "Carefully" pry out. (You can probably solve this with isopropyl alcohol - I read later).

#### Step 10 — assembly



• Install new battery. Reassemble the unit in reverse order of disassembly steps.

#### Step 11 — Outlook



- For me, the device worked well after the battery replacement. It was easy to turn on and off.
- Meanwhile, there was occasionally "freezing" the display while navigating, which could be remedied with a reboot. Maybe a hardware defect, which also affects the charging function. The new battery enough for about 2 hours navigation without charging cable too little, I think.
- Works permanently well. Also battery charge has gotten better. Maybe it was because the battery was too new.

Repeat the steps in reverse order to reassemble your device.