

Dexter 20V Multi-Tool Motor Replacement

Written By: Slava Korchmar




Dexter 20V Multi-Tool Motor Replacement

INTRODUCTION

This guide will show you how replace the motor in your tool

Step 1 — grinding head



• Remove the battery. Remove the screws on the tool body.

Step 2



• Disassemble the tool body. Remove the grinding head.

Step 3 — motor



• Remove the motor head.

Step 4



• Disconnect the motor from the grinding head.

To reassemble your device, follow the instructions in reverse order.