

Sony VAIO PCG-3E2L Hard Drive Replacement

The purpose of this guide is to help the reader replace the Hard Drive of the device.

Written By: Chengyang Chen



INTRODUCTION

This guide will aid readers to replace or upgrade Hard Drive of the device when the Hard Drive is not functioning properly.



TOOLS:

Phillips #00 Screwdriver (1)



PARTS:

• 2.5" Serial ATA Hard Drive (1)

Step 1 — Hard Drive



 Using a #00 Phillips screwdriver, remove the screw

Step 2



Remove the cover

Step 3



 Using a #00 Phillips screwdriver, remove the screw

Step 4







Grab the black plastic handle and pull the hard drive out slowly.

Only pull the hard drive horizontally. Do not lift the hard drive vertically

Step 5





Using a #00 Phillips screwdriver, remove the screw

To reassemble your device, follow these instructions in reverse order.