



Turtle Beach Ear Force XO Four Speaker Cone Replacement

Replace damaged or faulty speaker cones on the Turtle Beach Ear Force XO Four headset.

Written By: Evalyn Johnson



INTRODUCTION

If one of your Turtle Beach Ear Force XO Four speakers stops working, it may need to be replaced. To do so, follow this guide.



TOOLS:

- [Jimmy](#) (1)
 - [Phillips #0 Screwdriver](#) (1)
 - [Spudger](#) (1)
-

Step 1 — Ear Cushion



- Insert a flat metal object (such as iFixit's [Jimmy](#) tool) between the green and black plastic portions of the headset.

⚠ When working with electronics, it's important to choose a tool that's ESD-safe to avoid accidental damage to the device. The regular black nylon spudger or a plastic opening tool should be used whenever possible.

Step 2



- Carefully pry the plastic pieces apart, working your way around the ear cushion.

⚠ Be sure not to break the tabs on the back side of the ear pad!

Step 3



- Pull the loosened ear pad apart from the rest of the speaker.
- ☑ Pushing the pad and the speaker back together is the only step required for ear pad reassembly.

Step 4 — Speaker Cone



- Remove four 7.3mm PH0 screws.
- ⓘ As these screws are very small, it may be best to keep them in a plastic bag or other container.

Step 5



- Lift speaker cone off of the back casing.

⚠ Be gentle; the small wires connecting the speaker cone to the rest of the device may break if you pull too hard.

- Follow [iFixit's soldering guide](#) to remove the wires connected to the speaker.

To reassemble your device, follow these instructions in reverse order.