



Alan 48 Excel no or bad reception

Check Q104 and replace if necessary.

Written By: Ingo Ernsting



INTRODUCTION


Check Q104 and replace if necessary.

Step 1 — Transistor receiver



- Place of Q104 (KTK 161)
- Replace transistor.

Step 2



- Unwrap here

Repeat the steps in order to reassemble your device.