

trim loss

The cladding is removed.

Written By: Leonard Kesting



INTRODUCTION

It will be briefly shown how to remove the panel and a little tip's up there.

Step 1 — trim loss




• These two pins must be removed.

Step 2



 Here, a screwdriver or other stable thin object (in the picture: letter opener) can be helpful

Step 3



(i) TIP: if you remove the cladding more often (for example, for thorough cleaning), it may be helpful to provide the splints with some insulating tape, so the use of tools is unnecessary

Step 4



• The panel is now dismantled

Repeat the steps in order to reassemble your device.