



2003-2007 Honda Accord Auto Tensioner Replacement

A video tutorial on how to change the auto tensioner on a 2003-2007 Honda Accord.

Written By: eCuration



INTRODUCTION

A squeak in your engine bay is usually a first sign that the drive belt tensioner is going out.

Follow this video tutorial by YouTuber [NutzAboutBolts](#) to complete the replacement yourself.



TOOLS:

- [3/8" Drive Ratchet](#) (1)
- [14mm Deep Socket](#) (1)
- [12mm Deep Socket](#) (1)



PARTS:

- [Auto Tensioner](#) (1)

To reassemble your device, follow these instructions in reverse order.