

Huawei Y300 Vibrator Replacement

In this guide we are going to replace the...

Written By: Cordell



INTRODUCTION

In this guide we are going to replace the charging report on the Huawei ascend Y300 android smartphone. Before starting, it is a good idea to prepare an organized area to carry out the repair. It is also helpful to have a way of containing loose screws so they do not become lost.

TOOLS:


T4 Torx Screwdriver (1) Tweezers (1) Spudger (1)

Step 1 — Vibrator




Remove the back panel.

Step 2



• Remove the battery.

Step 3



• Use a T4 Torx screwdriver to remove the eight screws.

Step 4





• Pry the screen from the frame by utilizing a wedge.

 \triangle Avoid scratching the case.

Step 5





• Use the <u>tweezers</u> to remove the vibrator from the device.

To reassemble your device, follow these instructions in reverse order.