

HP Pavilion DM3-3010US Hard Drive Replacement

How to replace the hard drive

Written By: Somesh Rai



This document was generated on 2020-11-28 04:19:38 AM (MST).

INTRODUCTION

Hard drives are prone to failure, causing computer files to become inaccessible. This guide will explain how to replace a defective hard drive in the HP Pavilion DM3-3010US.



TOOLS:

- Phillips #0 Screwdriver (1)
- iFixit Opening Tools (1)



PARTS:

2.5" SATA Hard Drive (1)

Step 1 — Hard Drive



- Flip laptop over to back with the battery facing downwards.
- The battery is the silver cylinder located on the bottom of the laptop.

Step 2



- Locate switch for battery ejection.
- Battery ejection switch is located just above the left side of the battery.

Step 3



 Remove battery by sliding the battery ejection switch to the right and pulling the battery away from the laptop.

Step 4





- Using a plastic opening tool, remove the large square casing located on the bottom right side of the laptop.
- (i) The hard drive will be visible once the casing has been removed.

Step 5





- Using a Phillips #0 Screwdriver, remove each of the six Phillips #0 screws.
- (i) Four screws are located on each corner of the hard-drive.
- Two screws are located on the right side of the battery slot.

Step 6



 Remove old hard drive from its slot and replace with new hard drive, sticker side facing up. To reassemble your device, follow these instructions in reverse order.