



# Dyson V6 Motorhead Brush Bar Replacement

Brush bars have a history of failing, issues of them not rotating as well as wearing out.

Written By: Addie Hedge



## INTRODUCTION

Brushbar replacement, the brushbar may need frequent cleaning removing hair or other debris wrapped around the brush. After long use the bar may need replacement.



### TOOLS:

- [iFixit Opening Tools](#) (1)



### PARTS:

- [Dyson V6 and DC59 Motorhead Brush Bar](#) (1)

## Step 1 — Brush Bar



- Press the button to disconnect the vacuum head from the connecting pole.

## Step 2



- Turn the end cap counterclockwise using the iFixit Opening Tool.
- ⓘ If you do not have an iFixit Opening Tool, a quarter may be used instead.

### Step 3



- Pull the brush bar out of the housing.

To reassemble your device, follow these instructions in reverse order.