




Hamilton Beach 70740 Power Cord Replacement

Replacement of the power cord.

Written By: Travis Williams



INTRODUCTION

Replacement of the power cord. Make sure to keep the processor unplugged until finished with replacement.

TOOLS:

- [Phillips #2 Screwdriver](#) (1)
 - [Heavy-Duty Spudger](#) (1)
 - [Soldering Iron](#) (1)
-

Step 1 — Bowl and Lid




- Turn the bowl counterclockwise and lift.

Step 2 — Base



- Using a #2 Phillips head screwdriver, remove the two 11 mm screws from the base.
- Pull suction cups straight out.

Step 3




- Remove rubber caps using the heavy duty spudger.
- Remove the four 11 mm screws using the #2 Phillips head screwdriver.
- Pull base straight out.

Step 4 — Power Cord





- Using a #2 Phillips head screwdriver, remove the four 9 mm screws.
- From the open base pull the motor straight out.

Step 5





- Using the wire stripper crimping tool cut the black wire connection from the power cord to the motor and then rewire the new power cord to the motor.

Step 6





- Remove the two 12 mm screws using the #2 Phillips head screwdriver.
- Remove plastic piece.

Step 7



- Remove the three 12 mm screws using the #2 Phillips head screwdriver.
- Remove the plastic piece by pulling straight up.

Step 8



- Remove the power cord from the ground by removing the solder with the soldering tool.
- ☑ Solder the new ground from the new power cord.

To reassemble your device, follow these instructions in reverse order.