


2003-2007 Honda Accord Windshield Washer Pump Replacement

A video tutorial on how to change the windshield washer pump on a 2003-2007 Honda Accord.

Written By: eCuration



This document was generated on 2020-11-22 08:14:45 AM (MST).

INTRODUCTION

If you know that your windshield fluid reservoir is full but nothing comes out when engaged then it may be time to replace the washer pump.

Follow this video tutorial by YouTuber <u>NutzAboutBolts</u> to complete the replacement yourself.

TOOLS:

- 1/4" Drive Ratchet (1)
- 10mm Socket (1)
- Flathead Screwdriver (1)
- Torque Wrench (1)

PARTS:Windshield Washer Pump (1)

This document was generated on 2020-11-22 08:14:45 AM (MST).

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2020-11-22 08:14:45 AM (MST).