



Asus R510CA-OB01 Display Replacement

Use this guide to replace the display screen of your device.

Written By: Blanche Pinto




INTRODUCTION

Use this guide to replace the display screen of your Asus R510CA-OB01 laptop. In the event that your screen is faulty or blurred or you'd like to update to a screen with better resolution, you can use this guide to replace the display screen in your device.

TOOLS:


- [Spudger](#) (1)
 - [Phillips #0 Screwdriver](#) (1)
 - [iFixit Opening Tools](#) (1)
-

Step 1 — Display




- Open the device.
- Remove the black plastic squares on each side with a spudger.

Step 2





- Remove the two 5mm screws at each bottom corner of the display using a Phillips #0 screwdriver.

Step 3




- After the two screws are removed, use a plastic opening tool to remove the black cover around the screen.

Step 4



- Remove the four 5mm screws that attach the screen with a Philips #0 screwdriver.

Step 5



- Lift up the screen from the back of the laptop and then you will see a cable connected to the screen.
- You can simply disconnect the cable and insert a new screen.

To reassemble your device, follow these instructions in reverse order.