




iRobot Roomba 595 Pet Series Secondary Brush Replacement

How to quickly and safely replace the secondary side brush on your iRobot Roomba 595 Pet Series.

Written By: Dale Shirley-Potopsingh




INTRODUCTION

In this guide, the user will learn step by step how to safely take apart their iRobot Roomba with the intent of replacing their secondary side brush.

TOOLS:

- [Phillips #0 Screwdriver](#) (1)
-

Step 1 — Secondary Brush



- Flip the Roomba upside down. Using the Phillips #0 screwdriver, carefully remove the 5 mm screw holding the brush in place.

Step 2



- Gently pull the brush up and remove it from the device.

To reassemble your device, follow these instructions in reverse order.