

Vanagon Westfalia Ignition Switch Replacement

A video tutorial on how to change the 1983-1991 Vanagon T3 ignition switch.

Written By: eCuration



This document was generated on 2020-11-28 05:34:21 AM (MST).

INTRODUCTION

If you are experiencing no crank on key turn, it is likely either a dead battery or worn out ignition switch. If the battery is charged, please disconnect, and try replacing the ignition switch with a new one.

This video will show you how to remove the steering wheel in order to gain access to the ignition switch housing.

[video: https://www.youtube.com/watch?v=kgAxneoWejI]



TOOLS:

- 24mm 1/2" Drive Deep Socket (1)
- 1/2" Drive Ratchet (1)
- Phillips #2 Screwdriver (1)
- Flathead Screwdriver (1)
- Groove Joint Pliers (1)
- 13mm Wrench (1)



PARTS:

Ignition Switch Volkswagen 1974-1991(1)

To reassemble your device, follow these instructions in reverse order.