

OnePlus 3T Motherboard Connecting Cable Replacement

It is possible that motherboard connecting flex...

Written By: Witrigs



INTRODUCTION

[video: https://www.youtube.com/watch?v=-uUA97giQ3I]

It is possible that motherboard connecting flex cable of oneplus 3t got worn out and not effective any more. This repair guide video shows you how to fix it.



TOOLS:

Essential Electronics Toolkit (1) Tournevis Torx T2 (1)

To reassemble your device, follow these instructions in reverse order.